

FIELD INSPECTION REPORT

Date of Inspection : 3-12-2020		District : GAYA	
Division : Neemchak Bathani		Length (Km. : 1.80 Km	
Scheme/Programme: MIR-3054		MAINTENANCE Atri-bathani Rd to Sahoahri more via Bondi	
Package No. :		Road Id No. :	
Status of the Project :		Ongoing/Completed/Under Maintenance	
Work is a case of :		New Connectivity/Up gradation/Maintenance	
Sl. No.	Parameters to be checked		Remarks
1 Pavement			
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No ✓
f)	Contraction Joints provided or not (CC Pavement)		✓ Yes/No
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2 Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		✓ S/SRI/U
c)	Condition of railings/slab/approach for Bridges		NA S/SRI/U
3 Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		✓ Yes/No
4 Compliance History			
a)	Status of ATR's & any others.		NA

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—

Ram babu mah to
J.E

[Signature]
3-12-2020
J.E