FIELD INSPECTION REPORT

| Date of In | spection: | 3-12-20 | District: Cry a | |
|---|--|--|--------------------------|---------|
| Division: R-w-D. Crash Name of the Road: Kewali to | | | Length (km): 5.00 | · Will |
| | | | Charcoard Jamus & W | |
| A IV TO THE TOTAL OF THE TOTAL | rogramme: | MAINTENANC | | 5-p un |
| Package N | lo.: | | Road Id No.: | |
| Work is a case of: New Connec | | Ongoing/Compl | pleted/Under Maintenance | |
| | | New Connectivity/Up gradation/ Maintenance Parameters to be checked | | Remarks |
| Sl. No. | | Parameter | s to be checked | |
| 1. I | Pavement | | | |
| a) F | Road Junction condition | | | S/U |
| | Condition of Surfacing | | | /S/U |
| | Riding Quality | | | /S/U |
| | | | | /s/U |
| | Road Camber | | | / |
| e) V | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | Yes/No |
| | Contraction Joints provided or not (CC Pavement) | | | Yes/No |
| | Compaction of flank/slope & raincuts if any | | | Yes/No |
| 2. C | ross Draina | ge | | |
| a) C | Condition of head walls in Hume pipe culverts including its painting | | | S/SRI/U |
| b) Co | Condition of Abutment & Wing walls, Slab in RCC culverts | | | S/SRI/U |
| c) Co | Condition of railings/slab/approach for Bridges | | | S/SRI/U |
| 3. Re | ad Furnitu | re | | |
| a) W. sto | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | | | ¥es/No |
| 4. Co | Compliance History | | | |
| a) Sta | Status of ATR's & any others | | | AA |

Overall Rating

Satisfactory (S) Satisfactory but requires Improvement (SRI) Unsatisfactory (U)

(Signature)

NAME: AKribisa Kuma melif

DESIGNATION: A E