


FIELD INSPECTION REPORT


Date of Inspection : 02-12-2020	District: SAMASTIPUR
Division : SAMASTIPUR	Length (km): 2.40 KM
Name of the Road: Bhuidhara Chaur to via new dabas hote hue jel chaur.	
Scheme/Programme: MAINTENANCE	3054.
Package No.: 01 - SBD-2019-20	Road Id No.: 32010100860.
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No Yes
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U S
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NA

Overall Rating :

Satisfactory (S)	S ✓
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


 JE R.C.D. Samastipur-2
 NAME:


 04-12-2020
 (Signature)