

# FIELD INSPECTION REPORT

|                                                               |                    |
|---------------------------------------------------------------|--------------------|
| Date of Inspection : 3.12.2020                                | District: Keonjhar |
| Division : Mohana                                             | Length (km): 5.43  |
| Name of the Road: NH-30 to Katra Kala via Sonberha            |                    |
| Scheme/Programme: MAINTENANCE                                 |                    |
| Package No.: MR-H/19-20 Mohana                                | Road Id No.:       |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                    |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                    |

| Sl. No. | Parameters to be checked                                                                                        | Remarks        |
|---------|-----------------------------------------------------------------------------------------------------------------|----------------|
| 1.      | Pavement                                                                                                        |                |
| a)      | Road Junction condition                                                                                         | ✓<br>S/U       |
| b)      | Condition of Surfacing                                                                                          | ✓<br>S/U       |
| c)      | Riding Quality                                                                                                  | ✓<br>S/U       |
| d)      | Road Camber                                                                                                     | ✓<br>S/U       |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                    | ✓<br>Yes/No    |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                | Yes/No         |
| g)      | Compaction of flank/slope & raincuts if any                                                                     | Yes/No         |
| 2.      | Cross Drainage                                                                                                  |                |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                            | S/SRI/U        |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                        | S/SRI/U        |
| c)      | Condition of railings/slab/approach for Bridges                                                                 | S/SRI/U        |
| 3.      | Road Furniture                                                                                                  |                |
| a)      | Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained | 200m<br>Yes/No |
| 4.      | Compliance History                                                                                              |                |
| a)      | Status of ATR's & any others                                                                                    | No.            |

Overall Rating :

|                                             |   |
|---------------------------------------------|---|
| Satisfactory (S) ✓                          | S |
| Satisfactory but requires Improvement (SRI) |   |
| Unsatisfactory (U)                          |   |

NAME: Bhola Prasad Gubli

3.12.20  
(Signature) JB