

FIELD INSPECTION REPORT

Date of Inspection : 2.12.20		District: Kaimur
Division : Sahibganj		Length (km): 6.00
Name of the Road: Sahibganj to ujari Sikahi road		
Scheme/Programme: MAINTENANCE		
Package No.: MTR-N/2019-20/10		Road Id No.: 1030/502105
Status of the Project: Ongoing/Completed/Under Maintenance		profile correction
Work is a case of: New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U N/A
b)	Condition of Surfacing	✓S/U N/A
c)	Riding Quality	✓S/U N/A
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	✓S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges	✓S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Kumar
2.12.20
(Signature)

NAME: Sindora Kumar

DESIGNATION: T.E