


FIELD INSPECTION REPORT

Date of Inspection : 2.12.20		District: Raigarh
Division : Balakrishna		Length (km): 4.390
Name of the Road: Chimpur to Boodhara		
Scheme/Programme: MAINTENANCE		
Package No.: MR-N/2019-20/10		Road Id No.: 1030/502021
Status of the Project: Ongoing/Completed/Under Maintenance		profile correction
Work is a case of:		New Connectivity/Up gradation/ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U X/A
b)	Condition of Surfacing	S/U X/A
c)	Riding Quality	S/U X/A
d)	Road Camber	S/U X/A
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No X/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No X/A
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ✓
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	


 (Signature) 2.12.20

NAME: Alexander Kumar

DESIGNATION: A.E.