

FIELD INSPECTION REPORT


Date of Inspection : 3.12.2020		District: Kaimur	
Division : Mohauia		Length (km): 4.30	
Name of the Road: Pandey Pipra to T05 Road.			
Scheme/Programme: MAINTENANCE			
Package No.: MR-N/19-20 Mohauia		Road Id No.:	
Status of the Project: ☒ Ongoing/ ☐ Completed/ ☐ Under Maintenance			
Work is a case of: New Connectivity/Up gradation/ Maintenance			

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		☒ S/U
b)	Condition of Surfacing		☒ S/U
c)	Riding Quality		☒ S/U
d)	Road Camber		☒ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		☒ Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		No

Overall Rating :

Satisfactory (S) ☒	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Nitganand Singh


 03/02/20
 (Signature)