

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020		District: Bhopal	
Division : PIR0		Length (km): 11.960	
Name of the Road: Charbakhari 75 Mandiyon Road			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 10401800821	
Status of the Project:		Ongoing/Completed/Under Maintenance	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked	Remarks	
1. Pavement			
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank/slope & raincuts if any	Yes/No	
2. Cross Drainage			
a)	Condition of head walls in Hume pipe culverts including its painting	S/SR/L/U	-(N/A)
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SR/L/U	-(N/A)
c)	Condition of railings/slab approach for Bridges	S/SR/L/U	-(N/A)
3. Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4. Compliance History			
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

NAME:- Umesh Chaudhary

T.E

(Signature) 02/12/2020