

# FIELD INSPECTION REPORT

| Date of Inspection : 02/12/2020                               |                                                                                                                      | District: Bhajpur        |       |
|---------------------------------------------------------------|----------------------------------------------------------------------------------------------------------------------|--------------------------|-------|
| Division : DTRD                                               |                                                                                                                      | Length (km): 12.235      |       |
| Name of the Road: Chaptakhari To Rajapur Road                 |                                                                                                                      |                          |       |
| Scheme/Programme: MAINTENANCE                                 |                                                                                                                      |                          |       |
| Package No.:                                                  |                                                                                                                      | Road Id No.: 10401800822 |       |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                                                                                                                      |                          |       |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                                                                                                                      |                          |       |
| Sl. No.                                                       | Parameters to be checked                                                                                             | Remarks                  |       |
| <b>1. Pavement</b>                                            |                                                                                                                      |                          |       |
| a)                                                            | Road Junction condition                                                                                              | S/U                      |       |
| b)                                                            | Condition of Surfacing                                                                                               | S/U                      |       |
| c)                                                            | Riding Quality                                                                                                       | S/U                      |       |
| d)                                                            | Road Camber                                                                                                          | S/U                      |       |
| e)                                                            | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No                   | (N/A) |
| f)                                                            | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No                   | (N/A) |
| g)                                                            | Compaction of flank/slope & raincuts if any                                                                          | Yes/No                   | ✓     |
| <b>2. Cross Drainage</b>                                      |                                                                                                                      |                          |       |
| a)                                                            | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRU/U                  | (N/A) |
| b)                                                            | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRU/U                  | (N/A) |
| c)                                                            | Condition of railings/slab/approach for Bridges                                                                      | S/SRU/U                  | (N/A) |
| <b>3. Road Furniture</b>                                      |                                                                                                                      |                          |       |
| a)                                                            | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | Yes/No                   | ✓     |
| <b>4. Compliance History</b>                                  |                                                                                                                      |                          |       |
| a)                                                            | Status of ATR's & any others                                                                                         |                          |       |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | (S) |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

(Signature) *[Signature]* 03/12/2020

NAME: *Tarad Chaudhary*  
J.E