

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: MADHUBANI
Division : JHANTHARPUR	Length (km): 0.750 KM
Name of the Road: RED PATH TO MOHANPUR PATH	
Scheme/Programme: MAINTENANCE	MR (3054)
Package No.: MR-2/Jhantarpur/01/2018	Road Id No.: 31909800833
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: ☐ New Connectivity ☐ Up gradation ☒ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U Work in progress
c)	Riding Quality	S/U Work in progress
d)	Road Camber	S/U Work in progress
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Work in progress
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No ☒
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	☒
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
03/12/2020
(Signature)

NAME: SUJEET KUMAR

DESIGNATION: J.E.

Work section - Madhepur-1 & Jhantarpur