


FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: MADHUBANI
Division : JHANTHARPUR	Length (km): 2.10 km
Name of the Road: RED PATH TO CHOPTA PATH	
Scheme/Programme: MAINTENANCE	MR (3054)
Package No.: MR-2/Jhanttharpur/01/2018	Road Id No.: 31909800831
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	work in progress
c)	Riding Quality	S/U work in progress
d)	Road Camber	S/U work in progress
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No N/A
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	✓
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	


(Signature)

NAME: SUJEEET KUMAR

DESIGNATION: J.E.

work section - Madhepur - Jhanttharpur