

FIELD INSPECTION REPORT

DATE OF INSPECTION:	04/12/2020	DISTRICT:	PURNIA						
DIVISION:	DHAMDHA	LENGTH:	4.5 km						
NAME OF THE ROAD:	Bishanpur chok to Kishanpur Balua Rd.								
SCHEME/PROGRAMME:	MR-3054 (old)	MAINTENANCE	2nd yr. Maintenance						
PACKAGE No:	ROAD ID No.:								
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE ☒								
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE								
SLNO	PARAMETERS TO BE CHECKED	REMARKS							
1	PAVEMENT								
A	ROAD JUNCTION CONDITION	- S -							
B	CONDITION FO SURFACING	- S -							
C	RIDING QUALITY	- S -							
D	ROAD CAMBER	- S -							
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	- N.A -							
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	- N.A -							
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	yes.							
2	CROSS DRAINAGE								
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	- N.A -							
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	- N.A -							
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	- N.A -							
3	ROAD FURNITURE								
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	yes.							
4	COMPLIANCE HISTORY								
A	STATUS OF ATR's & ANY OTHERS	No any ATR							
OVERALL RATING	<table border="1"> <tr> <td>SATISFACTORY(S)</td> <td>- S -</td> </tr> <tr> <td>SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)</td> <td>/</td> </tr> <tr> <td>UNSATISFACTORY(U)</td> <td></td> </tr> </table>			SATISFACTORY(S)	- S -	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	/	UNSATISFACTORY(U)	
SATISFACTORY(S)	- S -								
SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	/								
UNSATISFACTORY(U)									

NAME: Shailendra Kumar
DESIGNATION: Assistant Engineer.

SIGNATURE
04/12/2020