

FIELD INSPECTION REPORT

DATE OF INSPECTION:	04/12/2020	DISTRICT:	PURNIA
DIVISION:	DHAMDAHA	LENGTH:	2.50 KM.
NAME OF THE ROAD:	Bishenpur chok to Bhawan Phulwaria.		
SCHEME/PROGRAMME:	MR (3054) Old	MAINTENANCE	
PACKAGE No:		ROAD ID No.:	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE		
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE		
SLNO	PARAMETERS TO BE CHECKED	REMARKS	
1	PAVEMENT		
A	ROAD JUNCTION CONDITION	- S -	
B	CONDITION FO SURFACING	- S -	
C	RIDING QUALITY	- S -	
D	ROAD CAMBER	- S -	
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	- N.A -	
F	CONTRACTION JOINTS PROVIDED OR NOT(CC PAVEMENT)	- N.A -	
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	YES.	
2	CROSS DRAINAGE		
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	- N.A -	
B	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	- N.A -	
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	- N.A -	
3	ROAD FURNITURE		
A	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M. STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	YES.	
4	COMPLIANCE HISTORY		
A	STATUS OF ATR's & ANY OTHERS	No any ATR.	
OVERALL RATING			
	SATISFACTORY(S)	- S -	
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	/	
	UNSATISFACTORY(U)		

Shailendra Kumar
NAME:
DESIGNATION: Asstt. Engineer.

SIGNATURE
04/12/2020