

FIELD INSPECTION REPORT

Date of Inspection :	04.12.2020	District:	SAPAW
Division :	MARHAURA	Length (km):	1.70 km
Name of the Road:	Jahri Pakri to Koriya Path under 354 (MR)		
Scheme/Programme:	MAINTENANCE		
Package No.:	Road Id No.: 31306500826		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		
Sr. No.	Parameters to be checked	Remarks	
1.	Pavement		
a)	Road Junction condition	S/U	
b)	Condition of Surfacing	S/U	
c)	Riding Quality	S/U	
d)	Road Camber	S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA	
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA	
g)	Compaction of flank/slope & raincuts if any	Yes/No NA	
2.	Gross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA	
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA	
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No	
4.	Compliance History		
a)	Status of ATR's & any others	NA	

Overall Rating :

Satisfactory (S)	10
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Remarks

At some points surface damage due to heavy flood & rain at some places now road is motorable at damage points.

4/12/2020
(Signature)

NAME:

Deven Sankar

A.E.

DESIGNATION: