

FIELD INSPECTION REPORT

Date of Inspection: 2.12.2020		District: Katihar.	
Division : Katihar		Length (KM) : 4.1 km	
Name of Road:	Kosha - Morghenda road foldobhi to Saira Adibassi to		
Scheme/ Programme:	MAINTENANCE		
Package No.	Road ID No. 21105500823		
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/ Up Gradation/ Maintenance		
Sl.No	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction Condition	L S/U	
b)	Condition of Surfacing	L S/U	
c)	Riding Quality	L S/U	
d)	Road Camber	L S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	L Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	L Yes/No	
g)	Compaction of flank/slope & raincuts if any	L Yes/No	
2	Cross Drainage		
a)	Condition of headwalls in Humepipe culverts including its painting	L S/SRI/U	
b)	Condition of Abutment & Wings walls, Slab in RCC culverts	L S/SRI/U	
c)	Condition of railings/slabs/approach for Bridges	S/SRI/U N/A	
3	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/Km & 200m stone/ Pavement road markings are provided and maintained.	L Yes/No	
4	Compliance History		
a)	Status of ATR & any others	No	
Overall Grading:		Satisfactory (S)	S
		Satisfactory but requires Improvement(SRI)	
		Unsatisfactory (U)	

Name: Vijay Kumar
Designation: A.E. Katihar

R.W.D. Works Div., Katihar

(Signature)
3.9.2020