

FIELD INSPECTION REPORT

Date of Inspection : 03-12-2020	District: Gaya
Division : Sheeghati	Length (km): 11.20 KM
Name of the Road: Basachatti to Mohanpur	
Scheme/Programme: MAINTENANCE	M/R 3054
Package No.:	Road Id No.:
Status of the Project: ☒ Ongoing ☐ Completed ☐ Under Maintenance	
Work is a case of: ☒ New Connectivity ☐ Up gradation ☐ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement - At 150 Present work is stopped	
a)	Road Junction condition	Only road dressing work S/U
b)	Condition of Surfacing	done and some pots planned S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	N/A Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage - Not done Now	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture - Not done Now	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	—
Satisfactory but requires Improvement (SRI)	—
Unsatisfactory (U)	—


03-12-2020
(Signature)

NAME: Suresh Prasad Singh

DESIGNATION: A.E, Basachatti