FIELD INSPECTION REPORT

Date of Inspection: 02/12/2020 District: Nalande					
Division: Bilouchani			Length (km): 1.6 m h	12.11	
Name of	the Rand: Gop	albad-Kotra (Ahi	yarpur) path to Rupaspur P	ath	
	· · · · · · · · · · · · · · · · · · ·	MAINTENANCE			
Package	No.:	Y	Road Id No.:		
Work is	the Project:	Ongoing/Completed	I/Under Maintenance		
51. No.	Vork is a case of: New Connectivity/Up gradation/ Maintenance				
-				Remarks	
1.	Pavement				
a)	Rond Junction condition			~S/U	
b)	Condition of Surfacing			√s/U	
c)	Riding Quality			√s/U	
d)	Road Camber			√s/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				
f)	Contraction Joints provided or not (CC Pavement)			Yes/No	
g)	Compaction	Yes/No			
2	Cross Drain	age			
a)	Condition of head walls in Hume pipe culverts including its painting S/SR				
b)				S/SRI/U	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	
. 3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained Yes/No				
温4.1	Compliance History				
a)	Status of ATR's & any others			No	

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Mojib Ahmad

DESIGNATION: J.E.

Scanned with CamScanner