## FIELD INSPECTION REPORT

		FIELD INSTITE	and the second s	and the second second
Date of Ir	nspection: 6	112 12020	District: Nalanda	
Date of Inspection: 02/12/2020 Division: Biharchant			Length (km): 2.110	
iame of	the Rand: Go	palbad-Kothro	e path to Dhunki	of the second of the second
Scheme/I	rogramme:	MAINTENANCE		No. of the last of
Package	No.:		Road Id No.:	
	the Project:	Ongoing/Completes	d/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maint			Remarks	
51. No.	Parameters to be checked			Kemater
1.	Pavement			
a)	Rond Junction condition			√S/U
b)	Condition of Surfacing			S/U
				S/U
c)	Riding Quality			VS/U
d)	Road Camber			
<b>c</b> )	Whether free from defects such as visible cracks, exposed yes/No aggregates in case of CC Pavement.			
Ð	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			VYes/No
2	Cross Drain	age		
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			✓S/SRI/U
c)	Condition of railings/slab/approach for Bridges			S/SRI/U
3	Road Furni	ture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
34.5-	Compliance	History		
8)		R's & any others	A Company of the Comp	No
2)	James C		The second secon	

Overall Rating

Satisfactory (S)	5
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

NAME: Moji's Ahmad

:

DESIGNATION: J.E.

Scanned with CamScanner