FIELD INSPECTION REPORT

			La Company of the Com	
	spection: 02	2 12 2020	District: Patna	
Division:	Patna	Sampatchak	Length (km): 1.00 Km.	
	he Road: M	1-30 Sorangpi	uz to Chana colony	
	rogramme:	MAINTENANCE	New Meinterance Poli	W.
Package I	2.65		Road Id No.:	
	the Project:		ed/Under Maintenance WORK	NOT START
Work is a case of:		Name and Address of the Owner, which we have a second	/Up gradation/ Maintenance	
SI. No.	TH ATT	Parameters t	o be checked	Remarks
1.	Pavement			
a)	Road Junction condition			
b)	Condition of Surfacing			
c)	Riding Quality			
d)	Road Camber			
c)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			
Ŋ	Contraction Joints provided or not (CC Pavement)			
g)	Compaction of flank/slope & raincuts if any			
2.2	Cross Drain	age -NA		
a)	Condition of head walls in Hume pipe culverts including its painting			
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			
c)	Condition of railings/slab/approach for Bridges			
3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
美和 定	Compliance History WORK YET TO Start			
a)	Status of ATR's & any others			THE REAL PROPERTY.
Overall	Rating	Satisfactory (' WORK YET TO	start.
		Satisfactory b	out requires Improvement (SRI)	
		Unsatisfactor	y (U)	

(Signature)

NAME: SUPRITA RANI

Scanned with CamScanner