

FIELD INSPECTION REPORT

Date of Inspection:	2/12/20	District:	Barkhanga
Division:	Bizaul	Length(Km):	4.10 km
Name of Road:	Pokharam REO road to Chenghara		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No
f)	Contraction joints provided or not (CC Pavement)	✓Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whether sign boards/ Informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No✓
3	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating:

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name:

Designation:

File
2/12/20
JE

File
02/12/20
AE

(Signature)