

FIELD INSPECTION REPORT

Date of Inspection:	3/12/20	District:	Early Longg
Division:	Biraul	Length(Km):	2.14 Km
Name of Road:	Saktaram to Jyeshpur		
Scheme/Programme:	Maintenance		
Package No.	3054 MR	Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
1	Pavement	✓S/U
a)	Road Junction condition	S/U✓
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	~Yes/No
f)	Contraction joints provided or not (CC Pavement)	~Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No✓
2	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
3	Road Furniture	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No✓
3	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating:
Some, surface length is damaged due to load 2020 yrs.

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	SRI
Unsatisfactory (U)	

Name:
Designation:

3/12/20
JL

4/12/20 (Signature)
AE