


FIELD INSPECTION REPORT

Date of Inspection:	3/12/20	District:	Bardhaman
Division:	Biraul	Length (Km)	2.14 Km
Name of Road:	Bhadra to Nandigram		
Scheme/Programme:	Maintenance ✓		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road function condition		
b)	Condition of Surfacing	✓ S/U	
c)	Binding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ S/U	
f)	Contraction joints provided or not (CC Pavement)	Yes/No	
g)	Compaction of flank /slope & raincuts if any	Yes/No ✓	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whether sign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No ✓	
3	Compliance History		
a)	Status of AIT's & any others	No	
Overall Rating:			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		SRI	
Unsatisfactory (U)			


 3/12/20
 Name: Biraul
 Designation:


 03/12/20
 AE

(Signature)