

## FIELD INSPECTION REPORT

Date of Inspection:	4/12/20	District:	Barbhangga
Division:	Barbhangga	Length(Km):	1.55
Name of Road:	Siso west chark to 8180 east chark		
Scheme/Programme:	Maintenance		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance		
Work is a case of :	New Connectivity/Up gradation/ Maintenance		

S No.	Parameters to be Checked	Remarks
<b>1</b>	<b>Pavement</b>	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank /slope & raincuts if any	Yes/No
<b>2</b>	<b>Cross Drainage</b>	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U N.A
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U
<b>3</b>	<b>Road Furniture</b>	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	Yes/No No
<b>3</b>	<b>Compliance History</b>	
a)	Status of ATR's & any others	
Overall Rating:		
Satisfactory (S)		
Satisfactory but requires Improvement (SRI)		
Unsatisfactory (U)		

GISB in Box and earth work in Progress

Name:

Designation:

(Signature)

Pravin  
4/12/20