	FIELD INSPECTION REPORT	
DATE OF INSPECTION:	04/12/2020 DISTRICT: PUPNIA	
DIVISION:	DHAMDAHA LINGTH: 6.50 KM.	
NAME OF THE ROAD:	Dampara Dhamlaha Banmankhi puto Rd to Khanw	
SCHEME/PROGRAMME:	MR-3059 Old) MAINTENANCE - 2 nd year	
PACKAGE No:	ROAD ID No	
STATUS OF THE PROJECT:	ONGOING/COMPLETED/UNDER MAINTENANCE	
WORK IS A CASE OF:	NEW CONNECTIVITY/UP GRADATION/MAINTENANCE	
SLINO	PARAMETERS TO BE CHECKED	REMARKS
1	PAVEMENT	
Α	ROAD JUNCTION CONDITION	- 5 -
В	CONDITION FO SURFACING	- 3 -
C	RIDING QUALITY	- 5 -
0	ROAD CAMBER	- 5 -
E	WHETHER FREE FROM DEFECTS SUCH AS VISIBLE CRACKS, EXPOSED AGGREGATES IN CASE FO CC PAVEMENT	yus.
F	CONTRACTION JOINTS PROVIDED OR NOTICE PAVEMENT)	7.0
G	COMPACTION OF FLANK/SLOPE & RAINCUTS IF ANY	405
2	CROSS DRAINAGE	
A	CONDITION OF HEAD WALLS IN HUME PIPE CULVERTS INCLUDING ITS PAINTING	- N.M
В	CONDITION OF ABUTMENT & WING WALLS, SLAB IN RCC CULVERTS	- N.A .
C	CONDITION OF RAILINGS/SLAB /APPROACH FOR BRIDGES	- N.W -
3	ROAD FURNITURE	
Α	WHETHER SIGN BOARDS /INFORMATORY BOARD/ KM & 200 M STONES/PAVEMENT ROAD MARKING ARE PROVIDED AND MAINTAINED	405.
4	COMPLIANCE HISTORY	
Α	STATUS OF ATR'S & ANY OTHERS	No am ATIL
OVERALL RATING		
OVERALL RATING	SATISFACTORY(S)	-5-
	SATISFACTORY BUT REQUIRES IMPROVEMENT(SRI)	

Sharlendockuners VAME: Assortingined.

NAME: 4