

FIELD INSPECTION REPORT

Date of Inspection:	3.12.2020	District:	DARBHANGA
Division:		Length(Km):	3.5 K.M
Name of Road:	JOLIYARA TO SAHASPUR		
Scheme/Programme:	Maintenance M/R (3054) - II		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition		
b)	Condition of Surfacing	Two ft. below shoulder ✓ S/U	
c)	Riding Quality	✓ S/U	
d)	Road Camber	✓ S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓ S/U	
f)	Contraction Joints provided or not (CC Pavement)	✓ Yes/No	
g)	Compaction of flank /slope & raincuts if any	✓ Yes/No	
2	Cross Drainage	✓ Yes/No	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls , Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture	S/SRI/U	
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained	✓ Yes/No	
3	Compliance History		
a)	Status of ATR's & any others		
Overall Rating:			
Satisfactory (S) ✓			
Satisfactory but requires Improvement (SRI)			
Unsatisfactory (U)			

Name: HARE RAM

Designation: J.E

3.12.2020
JC

3.12.2020 (Signature)
A.E.