

FIELD INSPECTION REPORT

Date of Inspection:	02.12.2020	District:	DARBHANGA
Division:	DARBHANGA -2	Length(Km):	4.0
Name of Road:	NH-105 KHIRMA TO BINWARA		
Scheme/Programme:	Maintenance MIRC 3054		
Package No.		Road Id No.	
Status of the Project:	Ongoing/Completed/ Under Maintenance ✓		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		
S No.	Parameters to be Checked	Remarks	
1	Pavement		
a)	Road Junction condition	✓S/U	
b)	Condition of Surfacing Four pt pits in village road to binwar and water level	✓S/U	
c)	Riding Quality	✓S/U	
d)	Road Camber	✓S/U	
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement	✓Yes/No	
f)	Contraction Joints provided or not (CC Pavement)	✓Yes/No	
g)	Compaction of flank /slope & raincuts if any Raincuts due to flood	Yes/No	
2	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U	
b)	Condition of Abutment & Wing walls, Slabs in RCC culverts	S/SRI/U	
c)	Condition of railing /slabs/ approach for Bridges	S/SRI/U	
3	Road Furniture		
a)	Whethersign boards/ informatory/ cautionary Board / Km & 200m stones/ Pavement road markings are provided and maintained Partially maintained	✓Yes/No	
3	Compliance History		
a)	Status of ATR's & any others	N	
Overall Rating: SRI			
Satisfactory (S)			
Satisfactory but requires Improvement (SRI)		✓	
Unsatisfactory (U)			

Name: HARE RAM
Designation: T.E

2.12.2020
JLC

02.12.2020
(Signature) HARE