FIELD INSPECTION REPORT

| THE RESERVE THE PERSON NAMED IN COLUMN 2 IS NOT THE PERSON NAMED I | spection: | District: Gaya | District: Cayo | |
|--|--|--|-----------------------|--|
| ivision: | -1- | | Length (km): 13.90 KM | |
| lame of t | | Lockgrim To Koshila Road | | |
| Scheme/Programme: MAINTENA | | MAINTENANCE New Policy | ICE New Policy | |
| Package ! | No.: | Road Id No.: | | |
| Status of the Project: | | Ongoing/Completed/Under Maintenance | | |
| Work is | a case of: | New Connectivity/Up gradation/ Maintenance | 1777 | |
| Sl. No. | | Parameters to be checked | Remarks | |
| 1, | Pavement | Surface work not started | | |
| a) | Road Junctio | S/U | | |
| b) | Condition of | S/U | | |
| c) | Riding Quali | S/U | | |
| | | S/U | | |
| d) e) | Road Camber Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement. | | | |
| f) | Contraction Joints provided or not (CC Pavement) | | | |
| g) | Compaction of flank/slope & raincuts if any Yes/N | | | |
| 8) | Gross Drainage | | | |
| | Condition of head walls in Hume pipe culverts including its painting S/SRI/O | | | |
| 8) | Condition of Abutment & Wing walls, Slab in RCC culverts | | | |
| b) | Condition of | S/SRI/U | | |
| c) | Condition of railings/slab/approach for Bridges S/SRI/U | | | |
| 3. | Road Furn | ture | | |
| a) | Whether sign boards/informatory/cautionary Board/km & 200m Yes/N stones/Pavement road markings are provided and maintained | | | |
| | Compliance | BUIDIN | 140 | |
| | Control Contro | TR's & any others | | |

Overall Rating

| Satisfactory (S) | 3' |
|---|----|
| Satisfactory but requires Improvement (SRI) | |
| Unsatisfactory (U) | |

(Signature)

DESIGNATION: F. E. S.