

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020	District: Madhepura	
Division : RWD. Udaishungari	Length (km): 4.730	
Name of the Road: Alamnagar To Kesopur Path.		
Scheme/Programme: MAINTENANCE		
Package No.:	Road Id No.: 2100480080017	
Status of the Project: Ongoing/Completed/Under Maintenance		
Work is a case of: New Connectivity/Upgradation/ Maintenance		
Sl. No.	Parameters to be checked	Remarks
1.	Pavement	S/U
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	
2.	Cross Drainage	S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	
3.	Road Furniture	Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	
4.	Compliance History	No.
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	(S) 0.67
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

03/12/20
(Signature) J.E.

NAME: Ravish. Ranyan

J.E. Alamnagar.

FIELD INSPECTION REPORT

Date of Inspection : 03/12/2020		District: Madhepura	
Division : UdaKishanganj		Length (km): 4.730	
Name of the Road: Alamnagar to Keshopur Path			
Scheme/Programme: MAINTENANCE		Road Id No.: 2100480080017	
Package No.:		Status of the Project: ☒ Ongoing/Completed/Under Maintenance	
Work is a case of:		☒ New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		S/U
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		Yes/No
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		
2.	Cross Drainage		S/SRI/U
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		
3.	Road Furniture		Yes/No
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		
4.	Compliance History		HO
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	work not proper
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

(Signature)

E.T.
A.W. UdaKishanganj

NAME:
Ravi Ravi Ravi