

# FIELD INSPECTION REPORT

|                                                               |                     |
|---------------------------------------------------------------|---------------------|
| Date of Inspection : 3-12-2020                                | District: Gaya      |
| Division : Gaya                                               | Length (km): 2.42KM |
| Name of the Road: Gaya Sherghati Road To Poner                |                     |
| Scheme/Programme: MAINTENANCE                                 | New Policy          |
| Package No.:                                                  | Road Id No.:        |
| Status of the Project: Ongoing/Completed/Under Maintenance    |                     |
| Work is a case of: New Connectivity/Up gradation/ Maintenance |                     |

| Sl. No. | Parameters to be checked                                                                                             | Remarks    |
|---------|----------------------------------------------------------------------------------------------------------------------|------------|
| 1.      | Pavement                                                                                                             |            |
| a)      | Road Junction condition                                                                                              | ✓ S/U      |
| b)      | Condition of Surfacing                                                                                               | ✓ S/U      |
| c)      | Riding Quality                                                                                                       | ✓ S/U      |
| d)      | Road Camber                                                                                                          | ✓ S/U      |
| e)      | Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.                         | Yes/No NA  |
| f)      | Contraction Joints provided or not (CC Pavement)                                                                     | Yes/No NA  |
| g)      | Compaction of flank/slope & raincuts if any                                                                          | ✓ Yes/No   |
| 2.      | Gross Drainage                                                                                                       |            |
| a)      | Condition of head walls in Hume pipe culverts including its painting                                                 | S/SRI/U NA |
| b)      | Condition of Abutment & Wing walls, Slab in RCC culverts                                                             | S/SRI/U NA |
| c)      | Condition of railings/slab/approach for Bridges                                                                      | S/SRI/U NA |
| 3.      | Road Furniture                                                                                                       |            |
| a)      | Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained | ✓ Yes/No   |
| 4.      | Compliance History                                                                                                   |            |
| a)      | Status of ATR's & any others                                                                                         |            |

Overall Rating :

|                                             |     |
|---------------------------------------------|-----|
| Satisfactory (S)                            | 'S' |
| Satisfactory but requires Improvement (SRI) |     |
| Unsatisfactory (U)                          |     |

*Rupnarayan*  
3-12-20  
(Signature)

NAME: Chandra Shekhar Kumar  
DESIGNATION: JE