

FIELD INSPECTION REPORT

Date of Inspection : 02/12/2020	District: Patna
Division : Patna / Sampat Chak	Length (km): 1.00 km
Name of the Road: Chhoti pusa to Saldandhale via Pipra Path	
Scheme/Programme: MAINTENANCE - 20-14-15 (NR 3054)	
Package No.: 8	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance - Under maintenance.	
Work is a case of: New Connectivity/Up gradation/ Maintenance - Maintenance.	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	U
b)	Condition of Surfacing	U
c)	Riding Quality	U
d)	Road Camber	U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	S
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	Yes
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	Yes
c)	Condition of railings/slab/approach for Bridges	Yes
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	NO
4.	Compliance History	
a)	Status of ATR's & any others	Emergent work had been done Badly Damaged H.V. By FDR

Overall Rating :

Satisfactory (S)	U
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Note:- Road not possible to maintain by Routine maintenance becoz road badly damaged in 2019 Flood, whole length of road.

(Signature)

NAME:

DESIGNATION:

Sub-ig
02/12/20
AB, Sampat Chak
RWD Sub Division
Sampat Chak.

02/12/20
J.E.