

(9)

FIELD INSPECTION REPORT

Date of Inspection : 02/12/20		District: Patna.
Division : Patna / Samastipur.		Length (km): 2.20 km
Name of the Road: Saidaiyachak se. Kambadiak (Mithandak)		
Scheme/Programme: MAINTENANCE - 2014-2015		MR (3054)
Package No.: *	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance - 5yr maintain	
Work is a case of:	New Connectivity/Up gradation/ Maintenance - Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S
b)	Condition of Surfacing	S
c)	Riding Quality	S
d)	Road Camber	S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	N/A
f)	Contraction Joints provided or not (CC Pavement)	N/A
g)	Compaction of flank/slope & raincuts if any	S, Yes.
2.	Gross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S
c)	Condition of railings/slab/approach for Bridges	N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Y
4.	Compliance History	
a)	Status of ATR's & any others	-

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	X
Unsatisfactory (U)	X

NAME:

DESIGNATION:

Subdivs
02/12/20
AE, RWD
Sub-Division
Kambadiak.

(Signature)