## FIELD INSPECTION REPORT

Date of Inspection: 3-12-2020			District: Gaya  Length (km): 1:00	
Division: Gaya Name of the Road: Gaya Dobh. Main				
The same of the sa	Programme:	MAINTENANCE		CKING
Package No.:			Road Id No.:	
	the Project:	Ongoing/Complet	ed/Under Maintenance	
Work is	a case of:	New Connectivity	/Up gradation/ Maintenance	
SI No.		Parameters	to be checked	Remarks
I.	Pavement			
a)	Road Junction condition			√S/U
b)	Condition of Surfacing			✓S7U
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)				- Yes/No
f)	Contraction Joints provided or not (CC Pavement)			-Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2	Cross Drains	ge in a		
	Condition of head walls in Hume pipe culverts including its painting			-S/SRI/U
	Condition of Abutment & Wing walls, Slab in RCC culverts			.S/SRIA
	Condition of railings/slab/approach for Bridges			S/SRI/U
- S.	Roid Challus			
	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
	Compliance Europy			
	Status of ATR's & any others			
				T , .
yerall R	ating	Satisfactory (S	S)	'S'

Satisfactory (S)	<b>'S'</b>
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Chandra Steklar Kumir

DESIGNATION: JE