FIELD INSPECTION REPORT

		FIELD INSIDERTON	· · · · ·			
Date of I	espection:	District: PATNA				
Division		UR Length (km): 1.085	20.			
Vame of	the Road: Bi	wa shinala na				
Package	No .: MR/N/19-	Ongoing/Completed/Under Maintenance orgains	?.			
Status of	the Project:	Ongoing/Completed Ontol				
Work is	a case of:	New Collinectivity, QP	Remarks	7		
Sl. No.		Parameters to be checked		100		
i.	Pavement		CIL			
a)	Road Junction	n condition	S/J			
	Condition of		S/J0			
b)			S/J			
c)	Riding Qualit	y	S/J			
d)	Road Camber			ħ		
e)	Whether free	e from defects such as visible cracks, exposed case of CC Pavement.	Yes/No	N.E		
	Contraction J	oints provided or not (CC Pavement)	Yes/No _	1		
g)	Compaction of	of flank/slope & raincuts if any Work in hoggies	Yes/No			
2.	Cross Drain	age		4		
共市 经报告 证	Condition of	head walls in Hume pipe culverts including its painting	S/SRI/U	1		
a)	Condition of	Abutment & Wing walls, Slab in RCC culverts	S/SRI/U	-{10		
b)	Condition of	2 : 11:	S/SRI/U	717		
c)	Condition of	railings/slab/approach for Bridges		(*)		
3.	Road Furni	ture .	TERSON SHOWS IN A	4550		
a)	Whether sig	gn boards/informatory/cautionary Board/km & 200m ment road markings are provided and maintained	Yes/No	•		
4.	Compliance	History				
a)	Status of AT	TR's & any others				

Overall Rating

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Anil Kumar.)

63/12/20 A.E. Bilute (Ramesh Kumar Singh) (Signature)

NAME:

DESIGNATION: