

FIELD INSPECTION REPORT

Date of Inspection : 03.12.20		District: Gaya	
Division : Gaya		Length (km): 1.15 KM	
Name of the Road: Chapari village to Markhya Path			
Scheme/Programme: MAINTENANCE		New Maintenance Policy 2018	
Package No.: MR-N/19-20/Gaya/08		Road Id No.:	
Status of the Project: Ongoing/Completed/Under Maintenance		Ongoing	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	
Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		✓ S/U
b)	Condition of Surfacing		✓ S/U
c)	Riding Quality		✓ S/U
d)	Road Camber		✓ S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)		Yes/No N/A
g)	Compaction of flank/slope & raincuts if any		✓ Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		✓ S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges		S/SRI/U N/A
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	✓ Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		NO

Overall Rating :

Satisfactory (S)	S
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Harishankar

NAME:

Shamka
03.12.20
(Signature) J.E.