

FIELD INSPECTION REPORT

Date of Inspection :	31/12/20	District:	Gaya.
Division :	Imamganj.	Length (km):	2.20 K.m.
Name of the Road:	Gotibandh to Kabisha.		
Scheme/Programme:	MAINTENANCE ✓		
Package No.:	MR IN 19-20 Imamganj 05	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance work started		
Work is a case of:	New Connectivity/Up gradation/ Maintenance ✓		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U U
b)	Condition of Surfacing	S/U U
c)	Riding Quality	S/U U
d)	Road Camber	S/U U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No No.
f)	Contraction Joints provided or not (CC Pavement)	Yes/No Yes.
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes.
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U SRT.
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U SRT.
c)	Condition of railings/slab/approach for Bridges	S/SRI/U S
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No No.
4.	Compliance History	
a)	Status of ATR's & any others	No ATR.

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	U

Gyalsim
31/12/20
(Signature) A.E.

NAME: G. S. yaulw. AE (Damon)