

FIELD INSPECTION REPORT

Date of Inspection :	3/12/2020	District:	Gaya
Division :	Imanganj	Length (km):	1.5
Name of the Road:	Paraliya to Gamadwar		
Scheme/Programme:	MAINTENANCE		
Package No.:	MR-N/19-20, Imanganj-06	Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance		Not Started
Work is a case of:	New Connectivity/Up gradation/ Maintenance		Maintenance (New)

Sl. No.	Parameters to be checked		Remarks
1.	Pavement		
a)	Road Junction condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints provided or not (CC Pavement)		Yes/No
g)	Compaction of flank/slope & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its painting		S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts		S/SRI/U
c)	Condition of railings/slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m	Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	N/A

Subendrak
03.12.20
(Signature) J.E.

NAME: Subendrakumar
J.E, R.W.D, Imanganj