

FIELD INSPECTION REPORT

Date of Inspection : 3/12/2020	District: Gaya
Division : Imamganj	Length (km): 2.62
Name of the Road: Benke Bazar to Morhar river via Juri Baichunbigha.	
Scheme/Programme: MAINTENANCE	
Package No.: MR-N-19-20, Imamganj/03	Road Id No.:
Status of the Project: Ongoing/Completed/Under Maintenance	Not Started
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	N/A

Subendraray
03.12.20
(Signature) J.E.

NAME: Subendrakumar
J.E, R.W.D, Imamganj