FIELD INSPECTION REPORT

Date of Inspection:		3/12/20 District: PATNA			
Division:	DF	NAPUR	Length (km):	1.950	
Name of th	ne Road: Ph	arpur village	to Dihri	Nahar in	Konka
	ogramme:	MAINTENANCE		22	ros
		-20-Dana?us/02	Road Id No.:		
Status of the Project: Y		Ongoing/Completed/Under Maintenance New Connectivity/Up gradation/ Maintenance			
Sl. No.		Parameters to be checked			Remarks
A MALE PARTY TO THE TAIL	Pavement	1 41414			
A PROPERTY.	Road Junction condition				S/U
	Condition of Surfacing				S/U
	Riding Quality				S/U
	Road Camber				S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.				Yes/No
	Contraction Joints provided or not (CC Pavement)				Yes/No
g)	Compaction of flank/slope & raincuts if any				Yes/No
2.	Cross Drainage				
a)	Condition of head walls in Hume pipe culverts including its painting				S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	
c)	Condition of railings/slab/approach for Bridges				S/SRI/U
3.	Road Furniture				
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained				Yes/No
4.	Compliance History				
a)	Status of ATF	l's & any others			

Overall Rating

work not started.

Satisfactory (S)
Satisfactory but requires Improvement (SRI)
Unsatisfactory (U)

J.E. Bilda Anil kumar.)

03/12/20 A.E./R.WD

(Signature)

NAME:

DESIGNATION: