

14012 JUST STREET

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: Patha
Division : Baddh.	Length (km): 0.600 km.
Name of the Road: Baddh Moolahachok PMHSY Road to Bujak.	
Scheme/Programme:	MAINTENANCE
Package No.: MR-N/19-20/Baddh/04	Road Id No.:
Status of the Project:	☒ Ongoing ☐ Completed ☐ Under Maintenance
Work is a case of:	☐ New Connectivity ☐ Up gradation ☒ Maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U
b)	Condition of Surfacing	S/U
c)	Riding Quality	S/U
d)	Road Camber	S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No
f)	Contraction Joints provided or not (CC Pavement)	Yes/No
g)	Compaction of flank/slope & raincuts if any	Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & stones/Pavement road markings are provided and maintained	200m Main board & logo establn
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	"S"
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

Bishwajit Prasad Singh

NAME:

03.12.2021
(Signature)