

FIELD INSPECTION REPORT

(Block - Shahkud)

Date of Inspection :	03/12/2020	District : Bhagalpur
Division : Bhagalpur	Length (Km) :	4.95 km
Name of the Road :	Sahpur Amarpur PWD Road ke yahi shod Amba to Gajga via LEO Road Banjarpur more Sahpur.	
Scheme / Programme :	MAINTENANCE	
Package No. / Group No. -	14	Road Id No. : 20703201055
Status of the Project :	Ongoing / Completed / Under Maintenance	
Work is a case of :	New Connectivity / Up gradation / Maintenance	

SL. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Cmpaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing Walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards / informatory / cautionary Board / Km & 200m stones / Pavement road markings are provided and maintained.	✓ Yes / No
4.	Compliance History	
a)	Status of ATR's & any others	NO

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA

NOTE: Work has not been started yet.

NAME: Neeraj Kumar

DESIGNATION: J-E

rd
03/12/20
(Signature)