

FIELD INSPECTION REPORT

Block - pirpainti

Date of Inspection : 03/12/2020 District: Bhagalpur
 Division : Kachalgauon Length (km): 5 Km
 Name of the Road: pirpainti Bazaar to Nandi Groudi
 Scheme/Programme: MAINTENANCE New Maintenance policy
 Package No.: Road Id No.:
 Status of the Project: Ongoing/Completed/Under Maintenance ongoing
 Work is a case of: New Connectivity/Up gradation/ Maintenance maintenance

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	SA NA
b)	Condition of Surfacing	SA NA
c)	Riding Quality	SA NA
d)	Road Camber	SA NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No Yes
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U
c)	Condition of railings/slab/approach for Bridges	S/SRI/U
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Yes
4.	Compliance History	
i)	Status of ATR's & any others	No

Overall Rating :

Work just started.

Satisfactory (S)	8
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

Signature
 AE
 03/12/2020

NAME: