

New maintenance policy

Block:- pirpaniti

FIELD INSPECTION REPORT


Date of inspection :	03/12/2020	District:	Bhagalpur
Division :	Kahalgaon	Length (km):	3.81 Km
Name of the Road:	PMGSY Road Mathurapur Japua to Madhepura via Goghatta		
Scheme/Programme:	MAINTENANCE	New maintenance policy.	
Package No.:		Road Id No.:	
Status of the Project:	Ongoing/Completed/Under Maintenance	ongoing	
Work is a case of:	New Connectivity/Up gradation/ Maintenance	Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATRs & any others	No

Overall Rating :

work yet to be started

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA


 (Signature)
 AG

NAME: