## FIELD INSPECTION REPORT

		A THE PARTY OF THE	MI KELOKA	
ate of l	Inspection: 0	Info Db	stricts Bhogolpur	
Division: Kelalaan			Longth (len): 100 Kard	
Name of	the Road:	chartera Santha	1 pargans Road to	Majohe
Scheme	Programme:	MAINTENANCE	ow Maintance poli	T.
Package No.:			Road Id No.:	
Status of the Project: Ongoing/Com		Ongoing/Completed/Uno	icu onder manne	
		The state of the s	Connectivity/Up gradation/ Maintenance + law Parameters to be checked	
Sl. No.		Parameters to be c	necked	Romarks
1.	Pavement	The state of the s	Charles Charles	S/U
a)	Road Junction condition			
b)	Condition of Surfacing			SAU
c)	Riding Quality			S/U
d)	Road Camber			S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.			Yes/No
f)	Contraction Joints provided or not (CC Pavement)			Yes/No
g)	Compaction of flank/slope & raincuts if any			Yes/No
2., -	Cross Draina	and the second second second second second second second		
a)	Condition of head walls in Hume pipe culverts including its painting			Ş/SRI/U
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U
c)	Condition of railings/słab/approach for Bridges			SASRIJU
-3.	Road Furniture			
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained			
4.	Compliance History			
a)	Status of ATR's & any others			No
Overall F	Rating :	This road is	an tender proce	43.
		Satisfactory (S)		~ /
			ires Improvement (SRI)	44
	n. A	Unsatisfactory (U)		1

pending shire to court care

(Signature)

NAME: