

Old HR

Out of Maintenance

FIELD INSPECTION REPORT

Date of Inspection :	4-12-2020	District:	Bhagalpur
Division :		Length (km):	2.650km
Name of the Road:	Thakubasi Chowk Vdaygrambus Ekchari to Raipur Kha		
Scheme/Programme:	MAINTENANCE		
Package No.:		Road Id No.:	20703408019
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
4.	Compliance History	
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	NA
Unsatisfactory (U)	

This is under out of Maintenance. This road has been taken under new HR Rality
This is under Tender Process

NAME:

for J.E

(Signature)

4/12/20