

old MR

out of Maintenance

FIELD INSPECTION REPORT

Date of Inspection : 4-12-20		District: Bhagalpur	
Division : Khatgaon		Length (km): 3.806 km	
Name of the Road: Kashi to Ramjanibpur			
Scheme/Programme: MAINTENANCE			
Package No.:		Road Id No.: 20703408023	
Status of the Project:		Ongoing/Completed/Under Maintenance <u>Out of Maintenance</u>	
Work is a case of:		New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U NA
b)	Condition of Surfacing	S/U NA
c)	Riding Quality	S/U NA
d)	Road Camber	S/U NA
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No NA
f)	Contraction Joints provided or not (CC Pavement)	Yes/No NA
g)	Compaction of flank/slope & raincuts if any	Yes/No NA
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U NA
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U NA
c)	Condition of railings/slab/approach for Bridges	S/SRI/U NA
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No NA
Compliance History		
a)	Status of ATR's & any others	No

Overall Rating :

Satisfactory (S)	
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	NA

This is under out of Maintenance.
DPR Submitted to H&D Br.

04/12/20
S.E.

(Signature) *AE*

NAME: