FIELD INSPECTION REPORT

Date of Inspection : Division :		2/12/2020	2/12/2020 District : Kahalgaon Length (Km) :		Bhagalpur 1.17	
		Kahalgaon				
Name o	of the Road:	NH 80 To Go	palpur Railway Fatak			
Scheme / Programme		MAINTENANCE				
Packag	e No. :		Road Id No. : 20703	3408031		
Status of the Project :		Under Maintenance				
Work is	a case of :	Maintenance				
SI. No.	Parameters to be Checked		Remarks			
1	Pavement					
a)	Road Junction Condition			S/U	S	
b)	Condition of Surfacing			S/U	U	
c)	Riding Quality			Ś/U	S	
d)	Road Camber			S/U	S	
e)	Whether free from defects such as visible cracks, exposed aggregatesv in case of CC Pavement			Yes/No	Yes	
f)	Contraction Joints Provided or not (CC Pavement)			Yes/No	Yes	
g)	Compaction of flank/slope & raincuts if any			Yes/No	Yes	
2	Cross Drainage					
a)	Condition of head walls in Hume pipe culverts including its painting			S/SRI/U	NA	
b)	Condition of Abutment & Wing walls, Slab in RCC culverts			S/SRI/U	NA	
c)	Condition of railings/slab/approach for Bridges			S/SRI/U	NA	
3	Road Furniture					
a)	Whether sign board/informatory/cautionary Board/Km & 200m stones/Pavement road markings are provided and maintained			Yes/No	Yes	
4	Compliance Histor	y				
a)	Status of ATR's & any others				NO	

Overall Rating:

Satisfactory (S) —
Satisfactory but Improvement (SRI) —
Unsatisfactory (U)

Name:

(Signature