

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	Banka
Division :	Banka-2	Length (km):	1.530 km
Name of the Road:	Dupl. of Barahi Injction Dam Road to Khanni moor village		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/BA/BAN/19/0011	Road Id No.:	20703501005
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No Y
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U N/A
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No Y
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S 'Satisfactory'
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
02/12/2020
(Signature)

NAME: RAAMESH KUMAR

DESIGNATION: JE