

FIELD INSPECTION REPORT

Date of Inspection : 03.12.2020	District: BANKA
Division : Banka-1	Length (km): 2.56
Name of the Road: Amarpur - Bhagalpur Road - Bajjudih	
Scheme/Programme: MAINTENANCE	
Package No.: RM/BA/BAN/19/0010	Road Id No.: 20703502022
Status of the Project: Ongoing/Completed/Under Maintenance	
Work is a case of: New Connectivity/Up gradation/ Maintenance	

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	✓S/U
b)	Condition of Surfacing	✓S/U
c)	Riding Quality	✓S/U
d)	Road Camber	✓S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N.A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N.A
g)	Compaction of flank/slope & raincuts if any	✓Yes/No
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U ongoing
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U ongoing
c)	Condition of railings/slab/approach for Bridges	S/SRI/U ongoing
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	✓Yes/No
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	satisfactory (S)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

NAME: Jaimangal Rabidas
DESIGNATION: Ex. Engineer Banka-1

Rabidas
03.12.2020
(Signature)