

FIELD INSPECTION REPORT

Date of Inspection :	02-12-2020	District:	
Division :	BANKA-2	Length (km):	1.26 km
Name of the Road:	Bundir Mangalpur Dam Bogula Road to Korkhatikan		
Scheme/Programme:	MAINTENANCE		
Package No.:	RM/BA/BAN/20/003	Road Id No.:	20703502046
Status of the Project:	Ongoing/Completed/Under Maintenance		
Work is a case of:	New Connectivity/Up gradation/ Maintenance		

Sl. No.	Parameters to be checked	Remarks
1.	Pavement	
a)	Road Junction condition	S/U S
b)	Condition of Surfacing	S/U S
c)	Riding Quality	S/U S
d)	Road Camber	S/U S
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.	Yes/No N/A
f)	Contraction Joints provided or not (CC Pavement)	Yes/No N/A
g)	Compaction of flank/slope & raincuts if any	Yes/No on-going
2.	Cross Drainage	
a)	Condition of head walls in Hume pipe culverts including its painting	S/SRI/U on-going
b)	Condition of Abutment & Wing walls, Slab in RCC culverts	S/SRI/U N/A
c)	Condition of railings/slab/approach for Bridges	S/SRI/U N/A
3.	Road Furniture	
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained	Yes/No on-going
4.	Compliance History	
a)	Status of ATR's & any others	

Overall Rating :

Satisfactory (S)	S (Satisfactory)
Satisfactory but requires Improvement (SRI)	
Unsatisfactory (U)	

[Signature]
02/12/2020
(Signature)

NAME: RAMESH KUMAR

DESIGNATION: JE