

FIELD INSPECTION REPORT

Date of Inspection: 03.12.2020		District: Kishansant	
Division: Kishansant-1		Length(km): 4.70 km.	
Name of the Road: Ashanipal to Pipra via Hemmat Nagar.			
Scheme/Programme:		MAINTENANCE New MR	
Package No.: RM/KI/KIS/19/0001		Road Id No.:	
Status of the Project: ☒ Ongoing/Completed /Under Maintenance			
Work is a case of:		New Connectivity/ Up gradation / Maintenance	
S1. No	<u>Parameters to be checked</u>		Remarks
1.	Pavement		S/U
a)	Road Junction Condition		S/U
b)	Condition of Surfacing		S/U
c)	Riding Quality		S/U
d)	Road Camber		S/U
e)	Whether free from defects such as visible cracks, exposed aggregates in case of CC Pavement.		Yes/No
f)	Contraction Joints Provided or not (CC Pavement)		Yes/No
g)	Compaction of fland / shop & raincuts if any		Yes/No
2.	Cross Drainage		
a)	Condition of head walls in Hume pipe culverts including its Painting		S/SRI/U
b)	Condition of Abutment & Wing walls, slab in RCC culverts		S/SRI/U
c)	Condition of railings/Slab/approach for Bridges		S/SRI/U
3.	Road Furniture		
a)	Whether sign boards/informatory/cautionary Board/km & 200m stones/Pavement road markings are provided and maintained		Yes/No
4.	Compliance History		
a)	Status of ATR's & any others		

Overall Rating :

Satisfactory(S)	S
Satisfactory but requires Improvement (SRI)	-
Unsatisfactory(U)	-


 03.12.2020


 03.12.2020
 (Signature) JE

NAME: